



Your Scaffolding Company Logo & Address

Inspection Report

Date: 18/01/2023 12:10:56

Inspector Name: Gareth Williams

Report ID: 1812023-587c4f55

Job No: 1002

Quote No.: 1002

Customer: Building Site

Site Address: The Old Grange

Design Ref: N/A

Design By: Scaffolding Designs

Design Checked By: N/A

Scaffold Location: Gable end

Brief Description: N/A

Reason For Inspection: 7 Day inspection

Loading Class: 1.5 kN/m² Inside Board Loading: 0.75 kN/m²

Foundations/Ground Condition: Good

Sole Pads/Base Plates: Good

Standards: N/A

Ledgers: N/A

Longitudinal Bracing: Good

Ledger Bracing: N/A Plan Bracing: Yes

Putlogs & Transoms: All Present

Couplings: Good

Ladders: Gated Ladder

Ties: N/A

Boarding: Good

Guard Rails & Toe Boards: Good

Netting/Sheeting & Brick Guards: N/A

Overloaded?: No

Erected to TG20?: Yes

Fit For Purpose & Safe?: Yes

General Remarks: At the time of inspection no defects were noted.

Inspectors Signature:

ERECTION AND INSPECTION RECORD

Ref. No.: **CE 11151**

Structure to be used for (please tick applicable /)

Load Class 1 UDL 0.75 kN/m ² / 75 Kg/m ² <input type="checkbox"/>	Load Class 4 UDL 3.00 kN/m ² / 300 Kg/m ² <input type="checkbox"/>
Load Class 2 UDL 1.50 kN/m ² / 150 Kg/m ² <input type="checkbox"/>	Load Class 5 UDL 4.50 kN/m ² / 450 Kg/m ² <input type="checkbox"/>
Load Class 3 UDL 2.00 kN/m ² / 200 Kg/m ² <input checked="" type="checkbox"/>	Load Class 6 UDL 6.00 kN/m ² / 600 Kg/m ² <input type="checkbox"/>

! IF LAST INSPECTION EXCEEDS 7 DAYS REMOVE INSERT AND INFORM SUPERVISOR

Record of inspection to be completed by a competent person:

Time	Date	Signature
10:20	7.10.22	G. Johnson

